

GMR6-WW-BA Installation Instructions for Recessed Mounting.

Recessed Mount

1. Drill a 2-5/8" diameter hole. Be sure to make ample clearance around lamp. Ensure there is no insulation, or other materials on top of the light. Fixture height is 2-1/2"
2. Feed wires through hole and install fixture into drilled hole by compressing springs. (Fig 2) Make sure gimble is positioned for desired adjustability.
3. Wire in parallel to remote 12vdc driver. Striped lead is positive(+) lead.



Fig 1



Fig2

12VDC,

Dimmable with dimmable power supply and dimming switch. Can use either magnetic or electronic dimming power supplies. Note: Minimum 2 lights when using a magnetic power supply.

Indoor only

Test lights and connections before final install. Tuck loose wires back to avoid pinching with the springs. Make sure there is ample clearance above the fixture, and no insulation around the fixture.(Non IC Rated) LED light and its holder are designed to vent.

Fixture is for indoor use only. Connect all electrical leads per local codes. Fixture does get warm to the touch.(6 Watts) To reposition led lamps, turn off light to let fixture cool down.